



Diame ter	Width	Centers	Height	Shaft H.	Foot H.	Hole Dia.	Length	Clamp screw
D	W	B	H	h	G	S	L	
8	42	32	32.8	20	6	5.5	14	M 4
12	42	32	37.5	23	6	5.5	14	M 4
16	48	38	44	27	8	5.5	16	M 4
20	60	45	42	31	10	6.6	20	M 5
25	70	56	60	35	12	6.6	24	M 6
30	84	64	70	42	12	9	28	M 6
40	114	90	96	60	15	11	36	M 8

ALL DIMENSIONS IN MILLIMETRE

NO WARRANTY THAT THESE DRAWINGS ARE CORRECT IS EXPRESSED OR IMPLIED.

10 November 2007

www.CNCDirect.co.za

SHAFT SUPPORT (SH)